



MMNRT Il Veloce

Equipment Substitution Request

Received: 2023-11-04 09:05 CET

Request No: 02

Boat: Figaro 3 - Ita 1 - Fenaio - Pendibene Andrea

Request:

Old Equipment:

Code 0 Zaoli

New Equipment:

Code 0 north sails

Reason:

I opened code0 zaoli after it was taken to the sail loft for repairs. Despite this there are still severe holes and the adhesive does not hold on the sail. I ask to use North sails code because zaoli's code0 is not usable

Response: Approved

A second Code0 is issues to all boats

*Response By Luigi Bertini Printed at 2025-04-30 21:22
CEST*