



Mussanah Open Championship 2021

Equipment Substitution Request

Received: 2021-04-06 08:41 +04

Request No: 05

Boat: Laser Radial - Laser Radial - 211717 - LaserMcLaserFace

Request:

Old Equipment:

New Equipment:

Reason:

Rear mainsheet block rivet is insecure, has already been replaced before and there is severe corrosion so repair is not possible. Looks like it will break very soon.

Response: Approved

The rivet was found to be loose (evidence photographed) and change of boom permitted

*Response By Ajit Diaz Printed at 2025-05-01 05:32
+04*