



2025 Fireball World Championship

Equipment Substitution Request

Received: 2025-08-24 16:13 CEST

Request No: 05

Boat: FIREBALL - 14641 - Alan Blay

Request:

Old Equipment:

Standard superstar.mast

New Equipment:

Standard slenden mast



[17560447004876616041842558216722.jpg](https://www.fishbase.org/species/17560447004876616041842558216722) 4.91 MB

Reason:

Jib sleeve box broke during the start of the second race. All right tension came off the rig. we did not finish the 2nd race. Upon inspection. Not only is the jib box broken the jib halyard has cut into the mast.



[17560446343727478208143548535204.jpg](#) 4.41 MB



[17560446713195435989774520735134.jpg 2.93 MB](#)

Response: Approved

Response By Race office Cva Printed at 2025-09-08 21:36 CEST