



# Bermuda Keelboat

## Damage Report

**Reported:** 2024-10-05

**Races:** 1-4


**Boat:** IOD, Sail: 14, Bow: , Celerity

**Skipper:** Ned Johnston

---

**Pre-Existing Damage:** No Pre-existing Damage

Spinnaker halyard cleat on mast came off the mast and was lost overboard. Tiller extension piece that prevents it from rotating broke. Extension is still usable. Cleat for starboard jib sheet came loose. We screwed it back in but it might not stay tight. Spinnaker has a small tear (3") near port clew. Jib leech and foot cords tore through their sleeves. Jib needs to be replaced. Headknocker cleat was sagging away from boom at forward end. We've lashed it in place with a piece of spectra found on the boat.



**Contact:** Minor Contact

Solna's bow hit our port toe rail and shroud. Our bowman fended off to prevent greater damage.

**Damage:** No Damage:

**Repair:** No Repair Attempted

---