



Bermuda Keelboat Damage Report

Reported: 2024-10-06

Races: Sunday

Boat: IOD, Sail: 6, Bow: , Blitz

Skipper: IOD - USA GIBSON ISLAND 2 - Tom Price

Pre-Existing Damage: Minor Pre-existing Damage

Main window crack.

Contact: Minor Contact

Side to side bump at start with 11 Solna

Damage: Minor Damage:

Repair: No Repair Attempted

1. Main boltrope near main tack unstitched
 2. Main halyard up the mast
 3. Spin halyard core separated at cleat and dropped the Spinnaker in front of boat causing boat to run over the spinnaker.
 4. Spinnaker has one tear and head was torn off after boat ran over the spinnaker
-