Protest

Protest No: 01

Received At: 2024-05-16 21:31 EDT

1. Event Name: ABYC Club Racing

Protest On: 2024-05-16
Race No: Tiesdays race 1

2. Hearing Type

✓ Protest	Request to Reopen
Protest by RC	Reopening by PC
Protest by PC	Request for Redress
Protest by TC	Request for Redress by RC

3. Protestor

PHRF FS (Flying Sails) - 1 - CAN 20001 - Carrera - Charles Orchard

4. Protestees

1. PHRF FS (Flying Sails) - 1 - CAN 154 - Privateer - Charles Edgeworth

5. Incident

Time Place: Approaching first mark (mark #1)

Rules: Rule 10 - When boats are on opposite tacks, a port-tack boat shall keep clear of a starboard-tack boat.

Witnesses: Hammer time Pascual

6. Informing Protestee

Hail:
Hail When: After the collision. Acknowledged by the other skipper
Hail Comment: I intend to protest.
Red Flag:
Red Flag Comment
Other:
Other Comment:

7. Description Of Incident

Carrera on starbord tack travelling 3.5 knots hailed to Privateer on port tack "Starboard" when the boats were approximately 8 boat lengths apart. Carrera hailed again "starboard" at 4 boats lengths apart which was acknowledged by the other skipper. When it became apparent that there was going to be a collision, Carrera's skipper bore off sharply (45-60 degrees to avoid being T boned. Privateers bow struck carerra 3 inches in front of the aft stanchion. Crew members of Carrera fended off after the collision.

8. Damage Or Injury

No injuries were sustained. Carrera suffered deck to hull delaminatiin for about 6 inches just forward of the aft stanchion, damage to he top deck overhang about 8 inches of fiberglass delamination and a thumbnail size hole almost through (maybe 1 layer of fiberglass remaining.

Attachments