Protest by TC

Protest No: 01

Received At: 2023-10-31 18:31 +03

1. Event Name: 34th Marmaris International Race Week

Protest On: 2023-10-31

Race No: 3

2. Hearing Type

☐ Protest	Request to Reopen
Protest by RC	Reopening by PC
Protest by PC	Request for Redress
✓ Protest by TC	Request for Redress by RC

3. Protestor

Technical Committee

4. Protestees

IRC 4 - GREEN 5-43 - RUS 2113 - SYMFONY - ANTON TIMAKOV

5. Incident

Time Place: After race at the port

Rules: IRC Witnesses:

6. Informing Protestee

Hail	:

Hail When:

Hail Comment:

□ Red Flag:

Red Flag Comment

Other:

Other Comment: After the inspection by phone

7. Description Of Incident

After the race we made technical inspections to boat from fleet 1.

We found in boat Symfony the following inconsistence with her Standard IRC certificate:

- 1. The boat had no table inside infridging the certificate that states that all standard accomondation have to be on board during racing.
- 2. Black band on the top of the mast (P) on the certificate is 13.90 m and it was measured 14.03 m $\,$
- 3. Black band on the boom (E) on the certificate is 4.90m and it was measured 4.92m
- 4. The lenght of the spinaker pole (SPL) on the certificate is 4.18m and it was measured 4.22
- 5. The head sail max luff lenght (HLU max) on certificate is 13.77m and it was measured 14.29m

8. Damage Or Injury

Attachments

Protest No: 01 Printed: 31 Oct 18:31 RacingRulesOfSailing.org