



Received: 2022-07-08 05:30 IST

Request No: 04

Boat: ILCA 7 - IND 202018 - SANDEEP KUMAWAT

Request:

Old Equipment:
BOOM

New Equipment:
BOOM

Reason:

BOOM 024 STICKER NO, BOOM MAIN SAIL PULLY EYE GOT DAMAGED, PULLY EYE CAM'T BE REPAIRABLE THATS WHY REQUEST TO CHANGE BOOM, CHANGING WITH BOOM NO 022 STICKER NO. SAIL NO. 202017 AND BOOM STICKER NO. 022 NOT USING BECAUSE OUR BOAT IS DAMAGED. SO REQUEST TO USE BOOM STICKER NO. 022 FOR SAIL

Response: Approved

APPROVED FOR BOOM

Response By An Swami Printed at 2024-05-04 01:35 IST