



MMNRT II Veloce

Equipment Substitution Request

Received: 2023-11-02 18:54 CET

Request No: 01

Boat: Figaro 3 - Ita1 - Fenaio - Andrea Pendibene

Request:

Old Equipment:

Code 0 zaoli is damage. There is a big delamination for half of the sail. The leech is broken.



[IMG_1315.jpeg 3.5 MB](#)



[IMG_1321.jpeg 3.64 MB](#)



[IMG_1322.jpeg](#) 3.68 MB



[IMG_1327.jpeg 2.88 MB](#)



[IMG_1318.jpeg 2.74 MB](#)



[IMG_1310.jpeg 3 MB](#)



[IMG_1309.jpeg 3.63 MB](#)

New Equipment:

Code 0. North sail

Reason:

I ask to use the code 0 NS because the zaoli's code is damage. Alternatively i ask to have another code0 in good condition and usable for racing

Response: Approved

A second Code0 is issues to all boats