



PredictWind 2024 International Moth Class World Championships

Equipment Substitution Request

Received: 2025-01-08 10:00 NZDT

Request No: 26

Boat: Moth - NZL 5106 - George Lee Rush

Request:

Old Equipment:

Bieker V5, broken kevlar and sika on flap

New Equipment:

New bieker v5

Reason:

My front horizontal MH-V5 has failed at the flap hinge. The manufacturer Mackay Boats has confirmed the failure and wants to replace the foil with a like for like MH-V5. This failure is unforeseeable and at no fault of my own.

Response: Approved

It will be approved on condition that the broken foil is shown to Allan Punch, Richard Didham, Sam Barnet, Graeme Sutherland for inspection but not one of those from your Country then get Shaun Ritson for the sticker

*Response By Harold Bennett Printed at 2025-04-28 22:38
NZST*