

SB20 Asia Pacific Championship 2026



Equipment Substitution Request

Received: 2026-02-01 09:23 +08

Request No: 01

Boat: SB20 - LumiNUS - Faith Ning Koy - Tang Yang Heng Russell Chia

Request:

Old Equipment:

The old spinnaker leech cord has gone back into the sail itself. Serial number: 1887704



[image.jpg 4.75 MB](#)

New Equipment:

We are using a spare spinnaker with more suitable leech cord length. Serial number: 56137402



[image.jpg 5.04 MB](#)

Reason:

Our current spinnaker leech cord has went inside the spinnaker and we are unable to get the cord back out. Therefore we are changing our spinnaker to a spare one with a more suitable leech cord tension.

Response: Approved
