



Tasar World Championships 2026 in Kunigami

Equipment Substitution Request

Received: 2026-06-10 18:23 JST

Request No: 32

Boat: Tasar - M - JPN 2959 - Destino - Mahoro Sekiguchi

Request:

Old Equipment:

New Equipment:

New set of shroud pull back ropes.

New set of slider bearing balls.

Reason:

Shroud pull back rope skin has splitted and needs replacement on both sides. During replacing the shroud pull back rope, we accidentally undone the sliders and lost some bearing balls, so we will replace them as well.

Response: Approved

Repairs and replacements have been approved.

Re-measurement is not required. TC Kazu

Response By Kazuyuki Higashijima Printed at 2026-06-26 03:34 JST