



43 Copa del Rey MAPFRE - ORC European Championship

Question for Officials

Date: 2025-07-30

Question No: 11

Question For: Race Committee

Question:

Hello!

Our boat has mistakes in ORC cert. Reason is we rented boat and had complications for full examine of all details because boat was in Turkey Marmaris harbour but we stay in Estonia, i fly to Turkey for ORC cert complition but unfortunately turkish ORC measurer did not come on time when i was present, but day later when only owners stay there they completed free boards and leaning test and confirmed new SPL, but measurer did not followed my requeat measure as well Jib 1 again, because it is 3 year old, reasoning it that sail already has ORC lable. As well based on new sails we made for Copa del ray, we need change P measure 15700 and E measure 5200 on mainsail, which is matching our seils real measures and add stay sail to sails list (Smaller then biggest jib). As well sail nr in ORC cert is EST 615 but it is now SMR1023 so we need change that as well. I hope it is OK ti change our crew weight to 935 kg. It is making our value worse but is more fare to crew so they do not need keep strickt diet. We have booked measurement time with Zoran tomorrow morning 0900 where we hope clear all issues on board.

Answer:

Response By Rocio Lozano Printed at 2025-07-31 14:59