



Cascais SB20 World Champio

Equipment Substitution Request

Received: 2021-09-01 01:00 WEST

Request No: 04

Boat: SB20 - POR POR3733 - so fly - Peter Stratton

Request:

Old Equipment:

Need to haul out the boat in order to repair the traveller block

New Equipment:

Reason:

Response: Approved

Discussed the failure and the repair necessary; approved removal of the boat from the water overnight for repair work. no polishing of hull to be carried out; boat to return to the water 02/09/2021

*Response By John Outhwaite Printed at 2025-06-21 05:44
WEST*