



Rooster-Monautix Europa Cu Equipment Substitution Request

Received: 2021-09-24 02:00 CEST

Request No: 02

Boat: ILCA 6 - 219711 - Paige Caldecoat

Request:

Old Equipment:

Sail

New Equipment:

Sail (same amount of use)

Reason:

My sail tore above the clear window. I am unable to get it fixed as the hole is too large therefor I will need to swap sails.

Response: Approved

You can change your sail, this is fine.

*Response By Bence Borocz Printed at 2025-04-30 17:36
CEST*