## Sail India 2021

## **Equipment Substitution Request**

Received: 2021-12-13 05:30 IST

Request No: 05

**Boat: 470 - INDIA IND 8 - PRABHAKAR PRAVEEN** 

Request:

**Old Equipment:** 

Hull

**New Equipment:** 

Hull

Reason:

My trolley broke during the launch and damaged the hull. So the hull needs to be repaired.

**Response: Approved** 

Damage physically inspected before repair and after repair . Found totally satisfied

Response By Vishnu Chandrabose Printed at 2024-05-01 04:55 IST