

Italian J70 Cup - Punta Ala Equipment Substitution Request

Received: 2022-04-23 02:00 CEST

Request No: 07

Boat: J 70 - ITA 720 - Valhalla - Fabio De Rossi

Request:

Old Equipment: main gennaker

New Equipment: spare gennaker

Reason:

The main gennaker has broken.

Response: Approved

Response By Egidio Babbi Printed at 2024-05-03 07:39 CEST