



RS500 World Championship 2022

Equipment Substitution Request

Received: 2022-08-02 01:00 IST

Request No: 01

Boat: RS500 - 795 - No name - Steve Cockerill

Request:

Old Equipment:

The x frame on Rs500 hull 795 has broken and will no longer hold rig tension. The deck under the mast is flexing and is unstable and not safe to sail.

New Equipment:

RS have given us a charter boat hull and rudder. Our rudder will not fit. The sails and rigging will be from the original boat.

Reason:

We will be unable to continue racing in 795 safely and will have to go home. We would like to continue the regatta with the new hull please. It's not safe to sail the boat as the mast is about to go through the deck if we keep sailing.

Response: Approved

*Response By Mark Wood Printed at 2025-04-29 10:17
IST*