



European Championship A-Class

Equipment Substitution Request

Received: 2022-09-15 10:28 CEST

Request No: 02

Boat: A CAT - Open - POL 41 - Jakub SUROWIEC Surowiec

Request:

Old Equipment:

Port rudder

New Equipment:

POrt rudder, The same TYPE, shape, construction

Reason:

Old rudder stard to have a crack on the side, one meter from the top, what can result in a fatal failature

Response: Approved

Both old and new rudder inspected, same shape size and construction. Crack evident on old rudder with movement of crack evident when flexed

Printed at 2022-12-04 01:57 CET