



European Championship A-Class

Equipment Substitution Request

Received: 2022-09-15 10:28 CEST

Request No: 02

Boat: A CAT - Open - POL 41 - Jakub SUROWIEC Surowiec

Request:

Old Equipment:

Port rudder

New Equipment:

POrt rudder, The same TYPE, shape, construction

Reason:

Old rudder stard to have a crack on the side, one meter from the top, what can result in a fatal failature

Response: Approved

Both old and new rudder inspected, same shape size and construction. Crack evident on old rudder with movement of crack evident when flexed

Response By Graeme Harbour Printed at 2025-05-09 15:47 CEST