

# Received: 2024-08-07 17:05 CEST

## **Request No: 04**

Boat: CAN 625 - La Dolce Vita - Laventure Lauren Jason Leimieux

#### **Request:**

## Old Equipment:

T- foil rudder is cracking on the horizontal foils. Unsafe to sail with it and looking to swap for identical rudder.

# New Equipment:

Identical t- foil rudder that is undamaged.

## Reason:

Cracking on horizontal wings. Unsafe to use.

#### **Response: Approved**

*Response By Carmelo Paroli Printed at 2025-04-30 03:26 CEST*