

2024 ILCA Asian Cup

Equipment Substitution Request

Received: 2024-09-07 16:52 CST

Request No: 02

Boat: ILCA 6 - ILCA 6 Men + Masters + U19 - JPN JPN 222433 - 222433 - Shun Fujino

Request:

Old Equipment:

hit a rock under water



[image.jpg 2.13 MB](#)



[image.jpg 665 KB](#)



[image.jpg 1.9 MB](#)



[0db85c99-b415-4bde-add8-8ccd882094d6.jpeg](#) 206 KB



[94ff7203-896b-4c86-a88c-801002ffaf31.jpeg 164 KB](#)

New Equipment:

Replace another centerboard

Reason:

The approved centerboard hit a rock and damaged

Response: Approved

Damaged centreboard sighted

Replacement centreboard presented for inspection

Replacement approved

*Response By Aileen H Loo Printed at 2025-04-30 11:22
CST*