



# Tasar World Championships 2026 in Kunigami

## Equipment Substitution Request

Received: 2026-06-06 14:36 JST

---

**Request No:** 05

**Boat:** Tasar - N - 2999 - Yusaku Akiyoshi

---

### **Request:**

**Old Equipment:**

The size of the crack is around 5mm.

**New Equipment:**

Putting some gel cote on the crack.

**Reason:**

There is a very small crack at the ladder.



[IMG\\_9113.jpeg 1.73 MB](#)

---

**Response: Approved**  
Repairs are permitted