



Cadet World Championship

Equipment Substitution Request

Received: 2026-08-02 20:23 CEST

Request No: 22

Boat: CADET - WORLDS - 10072 - RINGO - Jack Benyan

Request:

Old Equipment:

.

New Equipment:

Rudder repair requires filling with epoxy glue

Reason:

Rudder repair - leading edge of rudder suffered crack in todays strong wind. Crack requires filling with epoxy glue.

Response: Approved

Please present for inspection prior to racing tomorrow.

Response By Katrina Ham Printed at 2026-08-07 13:38 CEST